

PICKENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
Pickens County					
93 QUICK STOP	PETRO	UST	BLWM		Site ID # 07261. RBCA Classification 3AC1. Conducting investigation/Risk Assessment.
AKS INC DBA E Z STOP FOOD STORE	PETRO	UST	BLWM		Site ID # 07281. RBCA Classification 5A1. Conducting investigation/Risk Assessment.
BUD KELLY BP	PETRO	UST	BLWM		Site ID # 07292. RBCA Classification 4AA1. Conducting investigation/Risk Assessment.
C L MARTINS EXXON	PETRO	UST	BLWM		Site ID # 07260. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
CENTRAL EXXON	PETRO	UST	BLWM		Site ID # 07262. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaiti.
CLEMSON CENTRAL LANDFILL	VOC	LF	BLWM		In assessment and monitoring phases. Permit # 391001-1102.
CLEMSON UNIVERSITY MOTOR POOL	PETRO	UST	BLWM		Site ID # 07064. RBCA Classification 4AA3. Monitored Natural Attenuation.
DUCKS	PETRO	UST	BLWM		Site ID # 07243. RBCA Classification 2BA7. Approved Monitored Natural Attenuation (MNA Awaiti.
EASLEY LANDFILL	VOC	LF	BLWM		In remediation phase. Permit # 391001-1101.
EASLEY OIL CO INC	PETRO	UST	BLWM		Site ID # 07241. RBCA Classification 4AA8. Awaiting Funding.
FORMER BILL REEVES STATION	PETRO	UST	BLWM		Site ID # 18876. RBCA Classification 4AA8. Awaiting Funding.
GRIFFIN GROCERY	PETRO	AGT	BOW		In assessment phase. In enforcement. New source in addition to AST releases.
HOLLINGSWORTH SACO LOWELL	METALS, VOC, BNA	LF	BLWM	SCD065053217	In remediation phase. CMS in progress. Plume is discharging to Western Creek and Middle Creek. Site is undergoing redevelopment, The Easley Site Trust is retaining the regulated units. The developed land will be known as "Easley Town Center."
HOT SPOT 4004	PETRO	UST	BLWM		Site ID # 12157. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
K&R NO 1 LLC DBA SUNOCO	PETRO	UST	BLWM		Site ID # 07298. RBCA Classification 1D4. Active corrective action.
KWIK FOOD STORE	PETRO	UST	BLWM		Site ID # 13153. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaiti.
LEGRONE LAW ENFORCEMENT CENTER	PETRO	UST	BLWM		Site ID # 12757. RBCA Classification 3BD3. Monitored Natural Attenuation.
MAIN ST EXXON	PETRO	UST	BLWM		Site ID # 07308. RBCA Classification 4AA1. Conducting investigation/Risk Assessment.
MARK IV AUTOMOTIVE	VOC	S/L	BLWM	SCD098405251	Fomerly Anchor Swan. Monitoring groundwater contamination. Remedial action plan required.

10/28/2008

PICKENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
MCKINNEY DODGE	PETRO	UST	BLWM		Site ID # 18133. RBCA Classification 2BA7. Approved Monitored Natural Attenuation (MNA Awaits).
MEDICAL CENTER	PETRO	UST	BLWM		Site ID # 07090. RBCA Classification 3BA7. Approved Monitored Natural Attenuation (MNA Awaits).
OHIO GEAR RICHMOND GEAR SC OPER REGAL	PETRO	UST	BLWM		Site ID # 07085. RBCA Classification 5A3. Monitored Natural Attenuation.
OWT INDUSTRIES - FORMER RYOBI	VOC	S/L	BOW		Recovery wells are operating.
PICKENS COUNTY CONCRETE CO	PETRO	UST	BLWM		Site ID # 07204. RBCA Classification 4BC3. Monitored Natural Attenuation.
PLEZ U STORE 3	PETRO	UST	BLWM		Site ID # 07302. RBCA Classification 4BC2. Free Product recovery only.
PUMPERS PREMIUM STORES 13	PETRO	UST	BLWM		Site ID # 10599. RBCA Classification 3BE5. Inactive.
REVA OF CLEMSON	PETRO	UST	BLWM		Site ID # 07318. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
ROPER 66	PETRO	UST	BLWM		Site ID # 07178. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
SANGAMO WESTON- BRAZEALE	VOC, PCB	LF	BLWM	SCD980847297	In remediation phase, soils removed.
SANGAMO WESTON- CROSSROADS	VOC	LF	BLWM	SCD980847354	In monitoring phase. Remedial Design for GW remediation complete.
SANGAMO WESTON-PLANT SITE	PCB, VOC	LF	BLWM	SCD003354412	Soil remediation complete. Groundwater remediation system is operational. Private wells impacted (off-site). Plume is discharging to Twelve Mile Creek and Lake Hartwell.
SANGAMO/TWELVE- MILE/HARTWELL	VOC, PCB	PPL, LF	BLWM	SCD003354412	BLWM File # 50901. In monitoring and remediation phases. Plume is discharging to Twelve Mile Creek and Lake Hartwell.
SPINX 141	PETRO	UST	BLWM		Site ID # 10678. RBCA Classification 3BA7. Approved Monitored Natural Attenuation (MNA Awaits).
SPINX 403	PETRO	UST	BLWM		Site ID # 07270. RBCA Classification 2BA7. Approved Monitored Natural Attenuation (MNA Awaits).
SPINX 444	PETRO	UST	BLWM		Site ID # 07275. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
SYNERGY GAS CORP	PETRO	UST	BLWM		Site ID # 17080. RBCA Classification 5A1. Conducting investigation/Risk Assessment.
TIGER MART	PETRO	UST	BLWM		Site ID # 11311. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaits).
ZEE MART INC DBA ZEE MART	PETRO	UST	BLWM		Site ID # 07176. RBCA Classification 2BB2. Free Product recovery only.

10/28/2008

PICKENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
Total for Pickens	38				